



## IDAutomation SC5USB-D: Enable TAB as Suffix (Tab after Barcode)



### 1. Scan the Program Barcode




### 2. Scan the Suffix Barcode



### 3. To enable the TAB scan 0, 9 (or to disable TAB and set RETURN scan 0,D)



### 4. Scan Finish Barcode



### 5. Scan the Exit Barcode

